

# FLAMMABILITY TEST CERTIFICATE - 13613



Furniture Industry Testing Technology  
Russell Way, Bradford Road, Brighouse, HD6 4LX  
Tel: 01422 312250  
Email: charlotte@fitt-lab.co.uk

<b>Certificate ID:</b>	13613	<b>Piece:</b>	AN622727
<b>Quality:</b>	PIAZZA	<b>Colour:</b>	CAKE SPRINKLES
<b>Batch:</b>	230903	<b>FR Batch:</b>	C215639
<b>Fabric Type:</b>	Flat Woven Boucle	<b>Product Code:</b>	PIAZZA
<b>Date Received:</b>	07/02/2024	<b>Report Date:</b>	30/05/2024

The above details were supplied by the client, excluding unique ID and dates.

## TEST DETAILS

**Specification:** Schedule 4 Part 1 (Cigarette Test) & Schedule 5 Part 1 (Match Test) of the Furniture & Furnishings (Fire) (Safety) Regulations 1988 (as amended).

**Test method:** Test method: BS 5852 Part 1: 1979 Methods of test for the ignitability by smokers' materials of upholstered composites for seating.

**Pre-treatment:** Water soak procedure as detailed in The Furniture & Furnishings (Fire) (Safety) Regulations 1988 (as amended).

**Conditioning:**  $\geq 72$  hrs in ambient conditions then  $\geq 16$  hrs at  $20 \pm 5^\circ\text{C}$  and  $50 \pm 20\% \text{RH}$  prior to testing.

**Testing atmosphere:**  $15-30^\circ\text{C}$  /  $20-70\% \text{RH}$ .

**Filling:** VP45 non combustion modified foam as specified in the above Regulations.

## CONCLUSION

The sample supplied **MEETS** the requirements of The Cigarette Test ignition source 0 - Schedule 4, Part 1 of The Furniture and Furnishings (Fire) (Safety) Regulations 1988 (as amended). S.I.1324

The sample supplied **MEETS** the requirements of The Match Test ignition source 1 - Schedule 5, Part 1 - The Furniture and Furnishings (Fire) (Safety) Regulations 1988 (as amended). S.I.1324

COMPANY NAME: MODELLI FABRICS

CUSTOMER REFERENCE: 5760 FR

CERTIFICATE: 13613.1

### Decision Rules

Measurement uncertainty is considered when stating conformance to the specification. Where there is no annotation next to a result, the risk of false acceptance or rejection is 2.5%. Where the results are annotated with a U, the risk of false acceptance or rejection is 50%.

The certificate shall not be reproduced - except in full - without approval of the laboratory.

The following test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use.





TEST RESULTS

**Cigarette Test - Schedule 4 Part 1 (Ignition source 0) / BS5852-1:1979**

CIGARETTE TEST	1		2	
	LEFT		RIGHT	
SMOKE/SMOULDER DURATION (MIN:S)	19:05		17:17	
IGNITION / FLAMING OBSERVED WITHIN 60 MINUTES	NO	PASS	NO	PASS
PROGRESSIVE SMOULDERING OBSERVED WITHIN 60 MINUTES	NO	PASS	NO	PASS
COVER SPLIT	NO		NO	
MELTING	YES		YES	
DRIPPING	NO		NO	
CHARRING	YES		YES	
PROGRESSIVE SMOULDERING OBSERVED ON DISMANTLING AT 60 MINUTES	NO	PASS	NO	PASS
<b>OVERALL RESULT: PASS / FAIL</b>	<b>PASS</b>			

**Match Test - Schedule 5 Part 1 (Ignition source 1) / BS5852-1:1979**

MATCH TEST	1		2	
	LEFT		RIGHT	
APPLICATION TIME (S)	20		20	
IGNITION (S)	9		10	
COVER SPLIT (S)	0		0	
FLAME DURATION (S)	0	PASS	0	PASS
SMOKE END TIME (S)	23	PASS	25	PASS
SMOULDERING (S)	0	PASS	0	PASS
AFTER GLOW (S)	0	PASS	0	PASS
FORCIBLY EXTINGUISHED (S)	0	PASS	0	PASS
MELTING	YES		YES	
DRIPPING	YES		YES	
CHARRING	YES		YES	
PROGRESSIVE SMOULDERING OBSERVED ON IMMEDIATE DISMANTLING	NO	PASS	NO	PASS
<b>OVERALL RESULT: PASS / FAIL</b>	<b>PASS</b>			

Authorised by C Beever - Laboratory Manager

----- END OF REPORT -----

